DTC	B0113/42	Short in Front Side Squib (RH) Circuit (to B+)
-----	----------	--

CIRCUIT DESCRIPTION

The front side squib (RH) circuit consists of the airbag sensor assembly and front side airbag assembly (RH). It causes the SRS to deploy when the SRS deployment conditions are satisfied.

For details of the function of each component, see OPERATION on page RS-3.

DTC B0113/42 is recorded when a B+ short is detected in the front side squib (RH) circuit.


DTC No.	DTC Detecting Condition	Trouble Area
	• Short circuit in front side squib (RH) wire harness (to B+)	Front side airbag assembly (RH)
B0113/42	 Front side squib (RH) malfunction 	 Airbag sensor assembly
	 Airbag sensor assembly malfunction 	Wire harness

WIRING DIAGRAM

See page DI-272.


INSPECTION PROCEDURE











PREPARATION:

- (a) Connect the connector to the airbag sensor assembly.
- (b) Using a service wire, connect FR+ and FR- of the connector (on the front side airbag assembly side) between the front side airbag assembly (RH) and the airbag sensor assembly.
- (c) Connect negative (-) terminal cable to the battery, and wait at least for 2 seconds.

CHECK:

- (a) Turn ignition switch to ACC or ON and wait at least for 20 seconds.
- (b) Clear DTC stored in memory. (See step 5 on page DI-229)
- (c) Turn ignition switch to LOCK, and wait at least for 20 seconds.
- (d) Turn ignition switch to ACC or ON, and wait at least for 20 seconds.
- (e) Check DTC. (See page DI-229)

<u>OK:</u>

DTC B0113/42 is not output.


HINT:

Codes other than code B0113/42 may be output at this time, but they are not relevant to this check.

NG

Replace airbag sensor assembly.

ОК



HINT:

Codes other than code B0113/42 may be output at this time, but they are not relevant to this check.

NG

 \rangle Replace front side airbag assembly (RH).

ΟΚ

From the results of the above inspection, the malfunctioning part can now be considered normal. To make sure of this, use the simulation method to check. If the malfunctioning part can not be detected by the simulation method, replace all SRS components including the wire harness.