



5. Meter illumination is dark.

INSPECTION PROCEDURE

1 Remove cold cathode-ray tube.



2 Electrical continuity check of cold cathode-ray tube.



CHECK:

Is it continuity between connector 4 (HEATER+) and 3 (HEATER-) terminals of cold cathode-ray tube (upper or lower)?

No

Poor connector connection.

Yes

Faulty meter ECU.