

SRS AIRBAG

B00X1-02

PRECAUTION

The CENTURY is equipped with an SRS (Supplemental Restraint System) such as the driver airbag, front passenger airbag, front side airbag and rear side airbag. Failure to carry out service operation in the correct sequence could cause the SRS to unexpectedly deploy during servicing, possibly leading to a serious accident. Before servicing (including removal or installation of parts, inspection or replacement), be sure to read the precautionary notices in the RS section.